Консультации и техническое обучение от alflash

Вебинар как новое приложение Интернета

Участие в Вебинарах позволяет в удобной форме знакомиться с разнообразной и полезной информацией без отрыва от работы и семьи, а также и без особых финансовых затрат.

В онлайн можно проконсультироваться по конкретной тематике при диагностике и/или ремонте реального автомобиля, получить ответы на интересующие вопросы, участвовать в обсуждениях и проводить обучение.

В режиме реального времени доступны не только полноценный просмотр и прослушивание соответствующих информационных материалов, но и есть возможность задавать вопросы, комментировать содержание, общаться с коллегами и другими зрителями.

Проведение дискуссий и слётов по обмену опытом, «очных» конференций, организация Мастер-классов по обучению и передаче опыта – еще одна немаловажная возможность этого инструмента.

Технические требования.

- Наличие в компьютере последней версии Flash Player <http://get.adobe.com/ru/flashplayer/>
- Актуальные интернет браузеры MozillaFirefox <http://www.mozilla.com/ru/firefox/>
- ИЕ <http://www.microsoft.com/rus/windows/internet-explorer/>
- Наличие последней версии Java: <http://java.com/ru/>
- Минимальная скорость подключения к залу 56 Кб. Рекомендуемая скорость от 1 мегабита

ОВД-II и EOBD

Вчера, сегодня, завтра

Серия Вебинаров

Практическая диагностика системы управления двигателем

Новые “улики”,
заключительный “аккорд”
и ... продолжение

Тема дня

Mazda CX-7

и

код неисправности
системы VVT (DTC P0012)

8 - 15 - ... марта 2012

Mazda CX-7 "DTC P0012* CMP Timing Over-Retarded"

Generic OBD-II Scandata

SCAN TOOL - 2008 MAZDA CX-7 GRAND TOURING 2.3L (L4)

File Vehicle Options User Library Search View Instruments Help

88 DTC O2 I/M MODE MODE \$06 \$09 Scan GENERIC OBD II

	*Description	Value	Units		*Description	Value	Units
1	Absolute Load Value	17.2	%	2	Absolute Throttle Pos B	12.9	%
4	Absolute Throttle Pos D	31.4	%	5	Absolute Throttle Pos E	20.4	%
138	Absolute Throttle Position	12.5	%	35	Air Flow Rate MAF Sensor	2.71	gm/s_
32	Calculated Load	21.6	%	9	Catalyst Temp. Bank 1 Sensor 1	448.3	°C
14	Commanded EGR	0.00	%	13	Commanded Equivalence Ratio	1.000	
15	Commanded EVAP Purge	0.0	%	16	Commanded Throttle Actuator	4.3	%
17	Control Module Voltage	14.00	V	20	Engine Coolant Temp	79	°C
125	Engine RPM	702	RPM	139	Engine Vacuum	68.3	kPaA
75	Equivalence Ratio B1/S1	1.999		25	Fuel Level Input	38.8	%
23	Fuel Rail Pressure	42.8	kPaG	29	Fuel System 1 Status	CLSD LOOP	
37	Intake MAP	33.0	kPaA	38	Intake MAP Volts (Generic)	1.23	V
33	Long Term Fuel Trim B1	14.8	%	59	O2 (WR) Sensor Current B1/S1	6.539	mA
45	O2 Sensor Out Volts B1/S2	0.04	V	124	Relative Throttle Position	3.1	%
46	Rich/Lean Status B1/S2	LEAN		126	Short Term Fuel Trim B1	25.00	%

* Actual Valve Timing is Over-Retarded by 5 from the Target Valve Timing for 5 s when the OCV System Control is within the Feed-back Range.

Mazda CX-7 “DTC P0012 CMP Timing Over-Retarded”

Условия определения неисправности и возможные причины

DTC P0012	CMP Timing over-retarded
DETECTION CONDITION	<ul style="list-style-type: none"> • Actual valve timing is over-retarded by 5 ° (when the following conditions are met) from the target valve timing for 5 s when the OCV system control is within the feed-back range. <p>MONITORING CONDITION</p> <ul style="list-style-type: none"> — Engine speed is below 4,000 rpm. — Engine coolant temperature is above 70— 110 °C {158— 230 °F}. <p>Diagnostic support note</p> <ul style="list-style-type: none"> • This is a continuous monitor (CCM). • MIL illuminates if the PCM detects the above malfunction condition in two consecutive drive cycles or in one drive cycle while the DTC for the same malfunction has been stored in the PCM. • PENDING CODE is available if the PCM detects the above malfunction condition during the first drive cycle. • FREEZE FRAME DATA is available. • DTCs are stored in the PCM memory.
POSSIBLE CAUSE	<ul style="list-style-type: none"> • OCV malfunction • Low engine oil pressure • Spool valve in OCV is stuck in the retard position. • Variable valve timing actuator is stuck in the retard position. • Following oil runners are clogged or have leakage. <p>Oil runners</p> <ul style="list-style-type: none"> • Between oil pressure switch and OCV • Between OCV and variable valve timing actuator • In variable valve timing actuator <ul style="list-style-type: none"> • Loose timing chain or improper valve timing due to timing chain slippage • PCM malfunction

Устройство гидравлического привода системы переменного ГРМ

7. Turn the camshaft counterclockwise to align the notches on the variable valve timing actuator.

8. With the notches aligned, turn the camshaft clockwise 90 degrees.

9. Check the notches again.

A. If the notches are aligned, there is no problem with the variable valve timing actuator and this information is not applicable. Refer online instruction.

B. If the notches are NOT aligned, go to the next step.

Mazda CX-7 “DTC P0012 CMP Timing Over-Retarded”

Последовательность проверок при диагностике

Diagnostic procedure

STEP	INSPECTION		ACTION
1	VERIFY FREEZE FRAME DATA HAS BEEN RECORDED <ul style="list-style-type: none"> Has the FREEZE FRAME DATA been recorded? 	Yes	Go to the next step.
		No	Record FREEZE FRAME DATA on the repair order, then go to the next step.
2	VERIFY RELATED REPAIR INFORMATION AVAILABILITY <ul style="list-style-type: none"> Check for related Service Bulletins and/or on-line repair information availability. Is any related repair information available? 	Yes	Perform the repair or diagnosis according to the available repair information. <ul style="list-style-type: none"> If the vehicle is not repaired, go to the next step.
		No	Go to the next step.
3	VERIFY RELATED PENDING CODE OR STORED DTCS <ul style="list-style-type: none"> Is DTC P2088 or P2089 present? 	Yes	Go to the appropriate DTC troubleshooting procedure. (See DTC P2088[L3 WITH TC] or DTC P2089 [L3 WITH TC].)
		No	Go to the next step.
4	VERIFY ENGINE OIL PRESSURE <ul style="list-style-type: none"> Start the engine. Does the oil pressure warning light illuminate? 	Yes	Inspect engine oil pressure. (See OIL PRESSURE INSPECTION [L3 WITH TC].)
		No	Go to the next step.

STEP	INSPECTION	ACTION	
5	VERIFY TIMING CHAIN INSTALLATION <ul style="list-style-type: none"> Stop the engine. Remove the timing chain cover. Is the camshaft timing mark at the correct point? 	Yes	Go to the next step.
		No	Reinstall the timing chain, then go to Step 8.
6	INSPECT OCV FOR MALFUNCTION <ul style="list-style-type: none"> Stop the engine. Remove the OCV. Inspect the position of the spool valve in the OCV. Is the spool valve located at the valve retard position? 	Yes	VARIABLE VALVE TIMING MECHANISM IS NORMAL <p>Note</p> <ul style="list-style-type: none"> This DTC is detected as an intermittent concern. The intermittent concern might be removed using the cleaning mode of the variable valve timing control function. <p>Go to the next step.</p>
		No	Replace the OCV, then go to Step 8.
7	INSPECT ENGINE OIL RUNNER <ul style="list-style-type: none"> Inspect the following engine oil runners for clogging or leakage. <ul style="list-style-type: none"> Between the oil pressure switch and the OCV Between the OCV and the variable valve timing actuator In the variable valve timing actuator Is there any clogging or leakage? 	Yes	Repair or replace the suspected runner, then go to the next step.
		No	VARIABLE VALVE TIMING MECHANISM IS NORMAL <p>Note</p> <ul style="list-style-type: none"> This DTC is detected as an intermittent concern. The intermittent concern might be removed using the cleaning mode of the variable valve timing control function. <p>Go to the next step.</p>
8	VERIFY TROUBLESHOOTING OF DTC P0012 COMPLETED <ul style="list-style-type: none"> Make sure to reconnect all disconnected connectors. Clear the DTC from the PCM memory using the M-MDS. Turn the ignition switch off. Start the engine and warm it up completely. Is PENDING CODE for this DTC present? 	Yes	Replace the PCM, then go to the next step.
		No	Go to the next step.
9	VERIFY AFTER REPAIR PROCEDURE <ul style="list-style-type: none"> Perform the "After Repair Procedure". (See AFTER REPAIR PROCEDURE[L3 WITH TC].) Are any DTCs present? 	Yes	Go to the applicable DTC inspection. (See DTC TABLE[L3 WITH TC].)
		No	Troubleshooting completed.

Последовательность проверок при диагностике (продолжение)

Консультации и техническое обучение от alflash

Проверка TIMING ACTUATOR (фрагм.)

Verify that the groove of the rotor and notch of the cover on the variable valve timing actuator are aligned and fitted.

- If they are not aligned, rotate the crankshaft in the direction of engine rotation two times and verify that they are aligned.
 - If they will not align, replace the variable valve timing actuator.
- If under any condition, the variable valve timing actuator always makes a hitting noise directly after the camshaft exceeds maximum lift while rotating the crankshaft two times in the direction of engine rotation, replace the variable valve timing actuator as it has not been fixed.

Confirm that notch of the rotor and bump of the cover at the variable valve timing actuator are aligned and fitted. If the notch and the bump are not aligned, turn the crankshaft clockwise two rotations. Verify that the bump and the notch are aligned. " If the bump and notch are still not aligned, replace the variable valve timing actuator. " If, when turning the crankshaft, there is a hitting noise from the variable valve timing actuator each time the cam passes the fully lifted position, it means that the actuator is not secured. Replace the actuator.

Убедитесь, что вырез на роторе и впадина на крышке актюатора выровнены и совпадают. Если нет, то сделайте два оборота коленвала по часовой стрелке и проверьте снова. Если снова не совпадают, то замените гидравлический привод (актюатор). Если при вращении слышен скрежет и другие шумы - замените.

Установка TIMING ACTUATOR

- (1) Place alignment marks on the camshaft and variable valve timing actuator as shown in the figure so that the variable valve timing actuator is re-assembled in its original position.
- (2) Fix the camshaft in a vise.
- (3) Loosen the variable valve timing actuator installation bolt.

Проверка давления масляного насоса

Oil pressure (reference value) [oil temperature: 100 °C
297— 551 kPa {3.03— 5.61 kgf/cm²} [3,000 rpm]

Verify that the groove of the rotor and notch of the cover on the variable valve timing actuator are aligned and fitted.

- If they are not aligned, rotate the crankshaft in the direction of engine rotation two times and verify that they are aligned.
 - If they will not align, replace the variable valve timing actuator.
- If under any condition, the variable valve timing actuator always makes a hitting noise directly after the camshaft exceeds maximum lift while rotating the crankshaft two times in the direction of engine rotation, replace the variable valve timing actuator as it has not been fixed.

TSB: 0101011 от 23 февраля 2011

APPLICABLE MODEL: ... 2007 Mazda CX-7 vehicles...

Inspect the variable valve timing actuator for damage around the stopper pin cap or a missing stopper pin cap (B), spring and stopper...

...Turn the crankshaft clockwise so that the notches on the variable valve timing actuator can be checked.

...If the notches are aligned, there is no problem with the variable valve timing actuator.

Turn the camshaft counterclockwise to align the notches on the variable valve timing actuator.

With the notches aligned, turn the camshaft clockwise 90 degrees.

Если “метки” совпадают, то проблемы нет.

Поверните распредвал против часовой стрелке, чтобы их выровнять.

После этого поверните распредвал по часовой стрелке.

TSB: 0101011 от 28 ноября 2006 APPLICABLE MODEL: ... 2007 Mazda CX-7 vehicles

A pending code of P0012 is stored in PCM memory with no MIL illumination.

Reprogram the PCM to the latest calibration: L33L/M/N/P-18-88 (Labor: 0.3 Hour)

Waveform of OCV Operation

Результаты на 9 марта 2012:
трещина в месте концентратора
напряжения.

Вопросы:

- диапазон подвижности ротора
- состояние “фиксатора” положения?

Mazda CX-7

Photo by qyrec

Консультации и техническое обучение от alflash

<http://alflash.com.ua/avtovideo/>

CX-7 VVT Actuator Interior

“Ужасы нашего городка» или «Третий акт марлезонского балета”

Variable Timing Actuator ▲

One of the fissure damages ▲

Консультации и техническое обучение от alflash

<http://alflash.com.ua/avtovideo/>

CX-7 VVT Actuator Interior

“Ужасы нашего городка» или «Третий акт марлезонского балета”

The Rotor is cracked ▲

▲ Camshaft Housing & Sprocket

Консультации и техническое обучение от alflash

<http://alflash.com.ua/avtovideo/>

CX-7 VVT Actuator Interior

«Ужасы нашего городка» или «Третий акт марлезонского балета»

Stopper Pin Cap ▲

No comments ▲

Консультации и техническое обучение от alflash

<http://alflash.com.ua/avtovideo/>

CX-7 VVT Actuator Interior

“Ужасы нашего городка» или «Третий акт марлезонского балета”

Stopper Pin ▲

15/03/2015

Stopper Pin Hole

15/03/2015

Консультации и техническое обучение от alflash

<http://alflash.com.ua/avtovideo/>

CX-7 VVT Actuator Interior

(“Ужасы нашего городка» или «Третий акт марлезонского балета”)

Darkness ...

al tech page - www.alflash.com.ua

* Для справки

Консультации и техническое обучение от alflash
<http://alflash.com.ua/avtovideo/>

For example VVT Actuators Interior
(other)

▼ Toyota Avensis

Nissan X-Trail ▲

Причины* и следствия (послесловие)

- Низкий уровень профессиональной подготовки
- Отсутствие качественных БД
- Неправильная организация работ
- Безответственность
- Отсутствие нужного инструмента и/или диагностического оборудования
- Недостаточная мотивация

Note.

◀ L3 Engine 2002 MY
CMP & CKP Waveform

- For cylinder identification, the CMP sensor detects a camshaft angle of **30 degree** after the top dead center in cylinder No. 1.
- The wave form of CMP sensor output is shown in the figure.

- For detecting the crankshaft angle, the CKP sensor detects pulsation signals from pulse wheel
- The wave form of CKP sensor output is shown in the figure.

Note.

Voltage

Terminal	Voltage (V)	Condition
A	Below 1.0	Under any condition
B	4.8 or more	High output*
	0.8 or less	Low output*
C	B+	Under any condition

* : Output voltage varies with crankshaft rotation.

Voltage

Terminal	Voltage (V)	Condition
A	B+	Under any condition
B	Below 1.0	Under any condition
C	4.8 or more	High output*
	0.8 or less	Low output*

* : Output voltage varies with camshaft rotation.

▲ L3 Engine CX-7 2007 MY

CX-7 VVT Actuator Interior

(“Ужасы нашего городка» или «Третий акт марлезонского балета”)

Darkness ...

Консультации и техническое обучение от alflash

CX-7 VVT Actuator

Новый актюатор установлен

al tech page - www.alflash.com.ua

* Для справки

Консультации и техническое обучение от alflash

CX-7 new VVT Actuator

Oil Pump Chain

Консультации и техническое обучение от alflash

Self-made Camshaft alignment Tool

CX-7 VVT Actuator Interior

P.S.

P.S.S.

CKP vs. CMP vs. Ignition Waveform of Mazda CX-7 (known as good)

Data courtesy AVTEL

Проблемы других Mazda CX-7

No VVT Control

“Chinese” Quality Gasket

OEM Gasket

No bore!

В «левой» китайской прокладке головки нет отверстия для масляного канала

P.S.

Mazda CX-7 Printed Circuit Board Corrosion

“Системы переменного газораспределения”

(“30 лет в строю”)

- Назначение
- Варианты конструкции
- Причины неисправности и
- Методика и способы проверки (сканером и “вручную”)

Анализ данных режима Mode \$06

- Стратегия поиска причин наиболее массовых неисправностей
- Рекомендации и “тактика” проверок в ситуациях, когда ЕСМ не обнаруживает неисправности, хотя в автомобиле присутствуют проблемы.

“... Режим Mode#06 позволяет специалисту анализировать результаты выполнения ЕСМ самопроверок (MID, TID, CID, TLT), узнавать допустимые пределы и критерии неисправности (TLT), нынешнее состояние и остаточный моторесурс компонентов систем управления двигателем. Например, проблемы катализаторов, O2S, термостата, EVAP и прочего могут обнаруживаться при сравнении реальных параметров с пределами теста. А это позволяет оценить их “остаточный моторесурс” и степень изношенности...”

TID	TLT	CID	Test	Component	Test Value	Results	Test Limit	Limit Type	Unit	Application
\$01	0	\$01	Catalyst	Catalyst DETERIORATION Front to Rear	0.57 (\$0093)	FAIL	0.50 (\$0080)	Maximum	V	Front O2 Sensor Vehicles
\$01	0	\$01	Catalyst	Catalyst DETERIORATION Front to Rear	1.15 (\$0093)	FAIL	1.00 (\$0080)	Maximum	V	Air Fuel Sensor Vehicles
\$04	1	\$01	O2Sensor Heater	MAX Heater Current B1S1	0.744 (\$263E)	PASS	0.249 (\$0CCD)	Minimum	A	Oxygen Sensor Heater
\$04	1	\$02	O2Sensor Heater	MAX Heater Current B1S2	0.000 (\$0000)	FAIL	0.249 (\$0CCD)	Minimum	A	Oxygen Sensor Heater

Консультации и техническое обучение от alflash

Анонс Вебинара из серии “Диагностике электронных систем”

Diagnostics ScanTool Screen Save by al tech page

Data Logging Vehicle Options Help (http://alflash.com.ua/index.htm)

Diagnostic Trouble Codes | Live Data Meter | Live Data Graphs | Live Data Grid | O2 Sensors | Test OnBoard System | OnBoard Test Results

Support and Status of OnBoard System Tests

General Systems

Command Secondary Air Status: Not Reported

Power Take-Off Status: Not Reported

Battery Voltage: 13.49

Continuously Monitored Systems

OnBoard Module/System	Status
Misfire Monitoring	Complete
Fuel System Monitoring	Complete
Comprehensive Component Monitoring	Complete

Non-Continuously Monitored Systems Save Refresh

OnBoard Module/System	Status
Catalyst Monitoring	Complete
Heated Catalyst Monitoring	Not Supported
Evaporative System Monitoring	Complete
Secondary Air System Monitoring	Not Supported
A/C System Refrigerant Monitoring	Not Supported
Oxygen Sensor Monitoring	Complete
Oxygen Sensor Heater Monitoring	Complete
EGR System Monitoring	Not Supported

Monitored Test Results (Mode 6)

Test ID	Component ID	Value	Min Value	Max Val...	Units
(\$01) Catalyst Monitoring	(\$01) Malfunction Criteria for Catalyst Deterioration - Bank 1	0.062	0.000	0.500	Unitless
(\$02) Evaporative System...	(\$01) Undocumented CID	110.000	87.000	0.000	Unitless
(\$02) Evaporative System...	(\$02) Undocumented CID	88.000	64.000	0.000	Unitless
(\$02) Evaporative System...	(\$03) Malfunction criteria for 0.040" leak	0.046	0.000	1.466	mmHg
(\$02) Evaporative System...	(\$04) Malfunction criteria for 0.020" leak	0.000	0.000	11.679	mmHg
(\$04) Oxygen Sensor Mo...	(\$02) Undocumented CID	7472.000	2621.000	0.000	Unitless
(\$06) AF Sensor Monitoring	(\$011) Undocumented CID	6247.000	0.000	16384.0...	Unitless

A/F Ratio Sensor Bank 1 Sensor 1

MID	TID	Scaling	Description of Test Value	Minimum Test Limit	Maximum Test Limit
\$01	\$91	Multiplay by 0.003906 (mA)	A/F current	Minimum test limit	Maximum test limit

A/F Ratio Sensor Bank 2 Sensor 1

MID	TID	Scaling	Description of Test Value	Minimum Test Limit	Maximum Test Limit
\$05	\$91	Multiplay by 0.003906 (mA)	A/F current	Minimum test limit	Maximum test limit

Консультации и техническое обучение от alflash

Курс “OBD-II / EOBD: вчера, сегодня, завтра”

Диагностическая программа Toyota Techstream

Установка, возможности, режимы и правила использования,
практика и особенности применения

«Практическая диагностика системы управления двигателем»

al tech page - www.alflash.com.ua

«Практическая диагностика систем управления двигателем»

Серия Вебинаров,
форум,
онлайн консультации

ОBD-II и EOBD