

Tesla Powertrain Diagnostics - Service 1.1.42

File Views Perspectives Configuration Help

Screenshot by al tech page

Alert List

Currently Active Alerts

Potential Causes

Alerts

Alert History

Load Alert Log

Historic Causes

Alerts

1 BMS_f071 HV battery request not possible because of

Firmware Download to Vehicle

Obtaining Powertrain Hardware Configuration...This can take up to 2 minutes
Attempting to match a Powertrain Hardware Configuration ...
Successfully obtained Powertrain Hardware Configuration ID....
Make sure the charger is NOT connected!
Powering up the drive inverter...

Successfully powered up Drive Inverter
Transferring Firmware to Gateway....
Sending...
Write finished
Transferring boot image to Gateway....
Sending...
Write finished

Starting Powertrain Update

30 => 30 - skipping - succeeded.
Updating UDS Drive Inverter... 0.25.20 => 0.25.20 - skipping - succeeded.
Updating UDS BMS CPLD... 60 => 60 - skipping - succeeded.
Updating UDS BMS... 0.21.29 => 0.21.29 - skipping - succeeded.
Updating gateway... 0.61.49 => 0.61.49 - skipping - succeeded.
Updating log.cfg... succeeded.
Updating UDS Charger CPLD... 10 => 10 - skipping - succeeded.
Updating UDS CHG... 0.21.24 => 0.21.24 - skipping - succeeded.
Updating UDS THC... 0.17.6 => 0.17.6 - skipping - succeeded.
Updating UDS Pedal Monitor... 0.5.12 => 0.5.12 - skipping - succeeded.
Overall result: succeeded.
Rebooting...

Powertrain Update Process **succeeded. rebooting...**

100%