

al tech page

Odessa
WEB: www.alflash.com.ua

Diagnostic and Repair REPORT

Customer Name	Mr. D. N. Cher...	Phone	774-1...
Address	n/a	Vehicle Type	Truck
Color	4P2	Model	RX300
Mileage	113664	Year	1999
Hour	13:20	Engine	1MZ-FE
Date	18/05/2005	VIN	JT6HF10U4X0048807
Made By	Toyota Motor Corp. Japan		
License Plate	7NN-NN OE		

Check Engine lamp ON, Poor (Rough) Idle, Low Engine Power, Engine Surge During Driving

Diagnos Trouble Codes
Permanent DTC (1/1)

P0171
P0171 Sys.too Lean(Bank 1)

Use Up-Down Buttons

Clear memory Back

Figure 1

Freeze Frame

P0171 Sys.too Lean(Bank 1)

Calc. Load	Speed	Eng. Temp
45.87 %	74 kh	88 °C
ShtTrim	LngTrim	RPM
-1.56 %	43.74 %	2248 rm

Fuel System 1 **Fuel System 2**

Open Loop Open Loop

Clear memory Back

Figure 2

Diagnos Trouble Codes
Permanent DTC (1/0)

No
No Permanent Codes

Use Up-Down Buttons

Clear memory Back

Figure 3

Data compare

LONGFT1	%
-7.0	
SHRTFT2	%
1.5	

1 2 3 4 5 Hold Back

Figure 4 (after Repair)

Data compare

LONGFT1	%
-2.3	
SHRTFT2	%
-1.5	

1 2 3 4 5 Hold Back

Figure 5 (after Repair)

Graph Compare Record

RPM 3190.5 rpm

MAF 14.76 q/s

1 2 3 4 5 Hold Back

Figure 6 (after Repair)