

Subject

MIL ON with DTCs P1135 and P1155

Market

USA

Service Category

Vehicle Interior

Section

Meter/Gauge/Display

Applicability

1996-2003 Camry, Avalon - 1MZ-FE

APPLICABLE VEHICLES

1996-2003

Avalon

1996-2003

Camry

CONDITION

MIL ON DTCs P1135 and 1155 A/F sensor heater circuit malfunction

RECOMMENDATIONS

- Check ground connections on the intake manifold (see illustration below).
- Make sure connections are clean and secure.
- If these ground points are intact, inspect the individual ECM grounds.
- See Engine Control EWD to identify individual ECM grounds.

