Technical Service Information Bulletin

September 3, 2004

Title:

ENGINE BANK 1 AND BANK 2 A/F AND O2 IDENTIFICATION

Models:

Applicable Models



Introduction

This service bulletin provides information on the proper identification of engine bank 1 and engine bank 2 for correct A/F sensor and oxygen sensor replacement.

This bulletin contains information that identifies engine bank 1 and engine bank 2 on the following engines: 1MZ-FE, 3MZ-FE, 1UZ-FE, 2UZ-FE and 3UZ-FE.

- Bank 1 (B1) refers to the bank that includes cylinder No. 1.
- Bank 2 (B2) refers to the bank opposite bank 1.
- Sensor 1 (S1) refers to the sensor that is located before the catalytic converters.
- Sensor 2 (S2) refers to the sensor that is located after the catalytic converters.

Applicable Vehicles


- 1994 2003 model year ES 300 vehicles equipped with 1MZ-FE engine.
- 2004 model year ES 330 and RX 330 vehicles equipped with 3MZ-FE engine.
- 1998 2000 model year GS 400 vehicles equipped with 1UZ-FE engine.
- 2003 2004 model year GX 470 vehicles equipped with 2UZ-FE engine.
- 1990 2000 model year LS 400 vehicles equipped with 1UZ-FE engine.
- 2001 2004 model year LS 430 and GS 430 vehicles equipped with 3UZ-FE engine.
- 1998 2004 model year LX 470 vehicles equipped with 2UZ-FE engine.
- 1999 2003 model year RX 300 vehicles equipped with 1MZ-FE engine.
- 1992 2000 model year SC 400 vehicles equipped with 1UZ-FE engine.
- 2002 2004 model year SC 430 vehicles equipped with 3UZ-FE engine.


Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	_	_	-	-




Engine Bank Identification





Engine Bank Identification (Continued)



A/F and O2 Sensor Identification

